

CABENO Environmental Field Services, LLC
931 Country Creek Dr.
New Lenox , IL 60451
815-774-3747 phone / 815-774-3748 fax

February 27, 2025

Kevin Dark / Mark Heintz
Town of Munster
1005 Ridge Road
Munster IN, 46321

Mobile: (219) 836-6925
Email: [Mark Heintz <mheintz@munster.org>](mailto:Mark.Heintz@munster.org)
Mobile: 219-746-0083
Email: Kdark@munster.org

Scope of Work

Excavate to install new 6" HDPE line from GW-E22 to GW-E8,
Install sump by GW-E15, run 2 and 3 inch lines from new 6" to GW-E19, GW-E15, GW-E-11,
Partial repair of 2" line going to GW-E14

Location

Centennial Park
1005 S. Centennial Drive
Munster, IN 46321

Description	Units	Unit Cost	Actual Units	Totals
Mob/demob excavator and skidsteer	Lump Sum	\$1,000.00	1	\$1,000.00
Excavator with operator	Per Day	\$1,500.00	30	\$45,000.00
HDPE pipe and fittings	Lump Sum	\$19,225.00	1	\$19,225.00
Fusion equipment	Per Week	\$1,400.00	5	\$7,000.00
Mob/demob field crew X2	Per Day	\$400.00	30	\$12,000.00
Field technician labor X2	Per Hour	\$89.00	480	\$42,720.00
Skidsteer with operator and forks	Per Day	\$1,500.00	15	\$22,500.00
				\$148,445.00

Assumptions/Price Quote Notes

- CABENO is estimating between 5-6 weeks in the field to complete the work. There are multiple unknowns that can/will effect time onsite for the work that are out of control of CABENO: inclement weather, unmarked or mis-marked utilities (utilities for golf course and/or landfill) that get damaged during excavation work, repair of damaged utilities, and working around an active golf course are some examples.
- Because of the amount of unknowns for this project the estimate is a Time & Materials quote.
- If an unmarked or mis-marked utility is damaged CABENO will most likely not be making the repair, though we can assist. If the damaged utility is 2", 3", 4" or 6" HDPE or PVC CABENO will most likely be able to make repair however if the utility is a water/sprinkler line for golf course, electric/low voltage line for golf course or landfill, etc.. CABENO will not have capability to repair nor will be responsible for the repair.